


Complete Set for Multi-Row Modular Chassis

Article number
WSAIE4030R
WSAIE4040R
WSAIE5040R
WSAIE6040R
WSAIE7050R
WSAIE8060R
WSAIE1060R
WSAIE1080R
WSAIE1260R
WSAIE1280R



WSAIE4030R

No.		Pcs.	No.		Pcs.
A		2	F		1
B		2	G		2
C		2	H	M5x10mm 	8
D		2	I		2
E		4			

WSAIE4040R

No.		Pcs.	No.		Pcs.
A		2	F		1
B		2	G		2
C		2	H	M5x10mm 	8
D		2	I		2
E		4			

Complete Set for Multi-Row Modular Chassis

WSAIE5040R

No.		Pcs.	No.		Pcs.
A		2	F		1
B		2	G		2
C		2	H	M5x10mm 	10
D		2	I		3
E		4			

WSAIE6040R

No.		Pcs.	No.		Pcs.
A		2	F		1
B		2	G		2
C		2	H	M5x10mm 	12
D		2	I		4
E		4			

WSAIE7050R

No.		Pcs.	No.		Pcs.
A		2	F		1
B		2	G		2
C		2	H	M5x10mm 	12
D		2	I		4
E		4			

WSAIE8060R

No.		Pcs.	No.		Pcs.
A		2	F		1
B		2	G		2
C		2	H	M5x10mm 	14
D		2	I		5
E		4			

WSAIE1060R

No.		Pcs.	No.		Pcs.
A		2	F		1
B		2	G		2
C		2	H	M5x10mm 	18
D		2	I		7
E		4			

WSAIE1080R

No.		Pcs.	No.		Pcs.
A		2	F		1
B		2	G		2
C		2	H	M5x10mm 	18
D		2	I		7
E		4			

Complete Set for Multi-Row Modular Chassis

WSAIE1260R

No.		Pcs.	No.		Pcs.
A		2	F		1
B		2	G		2
C		2	H	M5x10mm 	20
D		2	I		8
E		4			

WSAIE1280R

No.		Pcs.	No.		Pcs.
A		2	F		1
B		2	G		2
C		2	H	M5x10mm 	20
D		2	I		8
E		4			

SAFETY INSTRUCTION:

Make sure to observe all specified tightening torques.

Incorrect torque values may lead to damage after assembly.